
79th St and Cicero Ave

< Eastbound and Southbound>

RLR Crash Data and Analysis

The table and chart below show a summary of motor vehicle crashes at the intersection of 79th St and Cicero Ave over a span of 5 years. The data from 2011 to 2013 show the period prior to the installation of RLR cameras. The data from 2014 show the year in which the cameras were installed. The data from 2015 show the year following the installation.

	Turning	Rear End	Angle	Ped./cyclist	Other	Total
2011	7	15	1	0	0	23
2012	10	17	0	2	2	31
2013	8	12	2	0	1	23
2014	10	9	0	0	1	20
2015	9	6	0	0	1	16



In 2013 the Average Daily Traffic (ADT) along 79th St reached 29,000 cars at the intersection of 79th St and Cicero Ave. During the same year the ADT along Cicero Ave reached 43,000 cars, according to IDOT.

In 2015 there was a decrease in ADT along Cicero Ave south of 79th St (36,000) and an increase north of 79th St (45,000). Along 79th St there was a decrease in both directions (27,000).

At the intersection of 79th St and Cicero Ave there were 23 accidents in 2011, 31 in 2012, 23 in 2013, 20 in 2014 and 16 in 2015.

Illinois Department of Transportation Division of Traffic Safety

Report Produced : 4/7/2017 9:26 AM

By: CENTRAL\SPERRYSJ

Page : 1 of 7

Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

Date	Weather	Roadway	Α	Injuries B	с	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201501204013 10/1/2015 5:44 PM				0			D		40.00	0050400 5000074										
10/1/2015 5:44 PM	Unknown	Unknown	0	U	0	0	Rear End	Unknown	46.69	2958403.5028371 1860293.53910079										
											Passenger	North	Slow/Stop In Traffic	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	2
											Pickup	North	Straight	In Traffic Motor	(Roadway) On	(UNK)	(UNK)	(UNK)	(UNK)	1
											Покар	North	Ahead	Vehicle In Traffic	Pavement	(OIVIC)	(OIVIV)	(ONIX)	(OIVIV)	
201501012315		_																		
1/Z/2015_4:35_PML _	_Clear	Dry			0			Daylight	46.73	2958395-02819867 1860448.17351571										
										1000 110111 00 101 1	SUV	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	3
											Passenger	West	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	Motor Vehicle In Traffic	On Pavement (Roadway	(UNK)	(UNK)	2
											Passenger	Northeast	Turning Left	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	1
201501035064														III IIailic						
2/18/2015 5:50 AM	Clear	Dry	0	0	0	0	Turning	Darkness, Lighted Road	46.73	2958395.18267898 1860449.24200452										
											Passenger	_West	_Straight Ahead	Motor Vehicle	_Intersectio.	-(TINK)	-(TINK)	_(JNK)	_ (UNK)	2
											Passenger	North	Turning Left	In Traffic Motor Vehicle	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	1
														In Traffic						
201501320967 2/27/2015 1:50 PM	Clear	Wet	0	0	0	0	Rear End	Daylight	46.73	2958395.33516623										
								3		1860448.54275227	Passenger	Northeast	Straight	Motor	On	(UNK)	(UNK)	(UNK)	(UNK)	2
											i doscrigo	Hortificast	Ahead	Vehicle	Pavement - (Roadway)	` ,	(Ortit)	(OIIII)	, ,	-
											Passenger	Northeast	Straight	Motor	Òn	(UNK)	(UNK)	(UNK)	(UNK)	1
													Ahead	Vehicle In Traffic	Pavement (Roadway)					
201501061064																				
3/30/2015 4:20 PM	Clear	Dry	0	0	0	0	Rear End	Daylight	46.73	2958395.62113735 1860448.71048746										
											Van/Mini- Van	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 4/7/2017 9:26 AM

By: CENTRAL\SPERRYSJ

Page : 2 of 7

Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

Date	Weather	Roadway		Injuries - B	 C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
											Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501329061																				
6/27/2015 12:3	0 AM Clear	Wet	0	0	0	0	Turning	Darkness, Lighted Road	46.73	2958401.94829033 1860448.94171881	Passenger	North	Straight	Motor	On	(UNK)	(UNK)	(UNK)	(UNK)	2
											· ·		Ahead	Vehicle In Traffic	Pavement (Roadway)	,	,	, ,	` ,	
											Passenger	South	Turning Left	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501148228		_	_	_	_	_														
7/29/2015-11:3	0-AM- Clear	Dry			0		l-u rning	Daylight	-46.73	-2958395.93194731 - 1860461.32637188										
										1000 101102001 100	Passenger	West	Turning Right	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Tractor With Semi- Trailer	North	Straight Ahead	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201501185361 8/31/2015 8:05	AM Clear	Dry	0	0	0	0	Sideswipe Same Direction	Daylight	46.73	2958395.23706358 1860457.47338519	-Bus-Over -	-0-4		-11-1	-⊕n	_/LINUX	- 4 IN II/A	- 4 IN II C	-41410	0
											15		Ahead	Vehicle	Pavement	-(ONK)	-(UNK)	-(UNK)	-(ONK)	2
											Passengers Passenger	South	Changing Lanes	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501399631																				
9/11/2015 11:3	0 AM Rain	Wet	0	0	0	0	Turning	Daylight	46.73	2958395.71145025 1860448.56231459										
										1000440.30231439	SUV	North	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Turning Left	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201501189996 9/17/2015 7:03	AM Clear	Dry	0	0	1	0	Turning	Daylight	46.73	2958395.47045665 1860448.54978577	SUV	East	Turning Left	Motor	Intersectio	(UNK)	(UNK)	(UNK)	(UNK)	2
														Vehicle In Traffic	n					
											Van/Mini- Van	West	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	1_

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 4/7/2017 9:26 AM

By: CENTRAL\SPERRYSJ

Page : 3 of 7

Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

Date	Weather	Roadway	A	Injuries B	с	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201501316227 10/2/2015 3:10 PM	Clear	Dry	0	0	1	0	Rear End	Daylight	46.73	2958401.71151382 1860448.92731504	SUV	North	Other	Motor	On	(UNK)	(UNK)	(UNK)	(UNK)	2
											Passenger	North	Other	Vehicle In Traffic Motor Vehicle In Traffic	Pavement (Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501408362 10/21/2015 8:15 AM	l Clear	Dry	0	0	0	0	Rear End	Daylight	46.73	2958393.30238375 1860448.43707159										
										1000440.43707139	Passenger	North	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
											Passenger	North	Straight Ahead	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
201501411375 11/3/2015 5:15 PM	Clear	Dry	0	0	0	0	Turning	Darkness	46.73	2958395.41854834 1860454.06430216	Poseeneer-	-Sneithe sot	— Turnina Left -		-0	/UNK\	-4 MW	_4 IN II/	- (1111K)	1
											J.		Straight Ahead	Vehicle In Traffic Motor Vehicle	Pavement	(UNK)	(UNK)	(UNK)	(UNK)	2
201501248692 11/16/2015 8:08 PN	1 Rain	Wet	0	0	0	0	Turning	Darkness, Lighted Road	46.73	2958395.71145025 1860448.56231459	Passenger	West	Turning Right	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	West	Turning Left	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201501262577 11/19/2015 11:45 PM	Clear	Dry	0	0	0	0	Turning	Darkness, Lighted Road	46.73	2958390.15224733 1860448.2733017	Tractor With Semi-	West	Turning Right	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	2
											Trailer SUV	West	Merging	In Traffic Motor Vehicle	(Roadway) On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
															(Roadway)					

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 4/7/2017 9:26 AM

By: CENTRAL\SPERRYSJ

Page: 4 of 7

Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

Date		Weather	Roadway	 A	Injuries - B	 С	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
	319914 2015 6:00 PM	Clear	Dry	0	1	0	0	Rear End	Darkness, Lighted Road	46.73	2958395.71145025 1860448.56231459										
									3			SUV	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	5
												Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	4
												Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
												Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
												SUV	West	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1

TOTAL:

16

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 4/7/2017 9:26 AM

By: CENTRAL\SPERRYSJ

16.7%

Page: 5 of 7

Coordinate Collision Diagram Report

1/1/2015 to 12/31/2015

For XCoordinate 2958395.71145025 : YCoordinate 1860448.56231459 | Foot Tolerance : 250 | County : Cook | Intersection Related: Intersections | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJ CRAS		PROPERTY DAMAGE CRASHES	KILLED		TOTAL IJURED	Α)	INJURIES	B INJURIES		C INJUR	IES
<u>16</u>	<u>0</u>	<u>0</u>	1	2) -	<u>13</u>	<u>0</u>		<u>3</u>			<u>0</u>	1		<u>2</u>
Type of Crash	Total	%	Dayof Wk	Total	%		Hour of Day	τ	otal	%		Vehicle Ty	/pe	Total	%
Rear End	6	37.5%	Monday	;	3 18	3.8%	Midnight		1	6.3%	Bu	s Over 15 Passengers		1	2.8%
Sideswipe Same Direction	1	6.3%	Tuesday		1 6.3	3%	05 AM		1	6.3%	Pa	ssenger		22	61.1%
Turning	9	56.3%	Wednesday	;	5 31	.3%	07 AM		1	6.3%	Pic	kup		1	2.8%
TOTAL:	16		Thursday	;	3 18	3.8%	08 AM		2	12.5%	SL	V		8	22.2%
			Friday	:	3 18	3.8%	11 AM		2	12.5%	Tra	actor With Semi-Trailer		2	5.6%
			Saturday		1 6.3	3%	1 PM		1	6.3%	Va	n/Mini-Van		2	5.6%
			TOTAL:	10	6	:	3 PM		1	6.3%	TC	TAL:		36	
							4 PM		2	12.5%					
							5 PM		2	12.5%					
							6 PM		1	6.3%					
						:	3 PM		1	6.3%					
							11 PM		1	6.3%					
							TOTAL:		16						
Weather Cond	Total	%	Light Cond	Total	%	;	Road Surface	Tota	ı	%	L	DIRP		Total	%
Clear	13	81.3%	Darkness		1 6.	3%	Dry		11	68.8%	E	ast		2	5.6%
Rain	2	12.5%	Darkness, Lighted Road		5 31	1.3%	Unknown		1	6.3%	N	lorth		11	30.6%
Unknown	1	6.3%	Daylight		9 56	6.3%	Wet		4	25.0%	N	ortheast		3	8.3%

TOTAL:

16

South

Illinois Department of Transportation Division of Traffic Safety

Report Produced : 11/6/2015 9:09 AM

By: CENTRAL\ADAMSCH

Page : 1 of 6

Collision Diagram

1/1/2014 to 12/31/2014

Date	Weather	Roadway	 A	Injuries B		Killed	Type of Crash	Light Condition	Mile	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201400079617 1/18/2014 2:50 PM	Snow	Snow or Slush	0	0	0	0	Rear End	Daylight	46.69										
										Passenger	East	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)) 1
										SUV	East	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201400081269 1/20/2014 7:45 PM	Clear	Snow or	0	0	0	00	Rear End	Darkness/ Lighted	46.69										
		Slush						Road		Truck Single Unit	South	Straight Ahead		On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										SUV	South	Slow/Stop In Traffic	Motor Vehicle	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201400012915 1/25/2014 12:31 PM	Clear	Wet	0	0	0	0	Rear End	Daylight	46.69										
										Truck Single Unit	North	Straight Ahead	Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	T-
										Passenger	North	Other	Motor Vehicle	(Roadway) On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	2
										Passenger	North	Other	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201400131417 3/3/2014 2:10 PM	Clear	Wet	0	0	0	0	Rear End	Daylight	46.69										
										Passenger	West	Skidding/Co ntrol Loss	Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										Pickup	West	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)) 2
201400164085 3/20/2014 7:08 PM	Clear	Dry	0	0	0	0	Turning	Darkness/ Lighted Road	46.69	Passenger	North	Turning Left	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	, 1
										-Passenger	-South	- Straight Ahead	- Motor	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	2 -

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 11/6/2015 9:09 AM

By: CENTRAL\ADAMSCH

Page : 2 of 6

Collision Diagram

1/1/2014 to 12/31/2014

Date	Weather	Roadway	Α	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201400044272 5/3/2014 2:48 PM	Clear	Dry	0	0	1	0	Rear End	Daylight	46.69										
										Passenger	South	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										Passenger	South	Slow/Stop In Traffic	In Traffic Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)) 2
										Passenger	South	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201400243051 5/6/2014-6:30-PM	- Clear						- Turnipo		-46-69-										
	O.Ga.	2.,	ŭ	Ů	Ü	Ü	· ag	zayg.n	10.00	Unknown	North	Straight Ahead	Motor Vehicle	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	, 1
										Passenger	East	Turning Left	In Traffic Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	2
201400244172		_											iii rraino						
5/7/2014 3:30 PM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69	Passenger	East	Turning Left	Motor	On	(UNK)	(UNK)	(UNK)	 (UNK)	. 1
										rassenger	Lasi	running Len	Vehicle In Traffic	Pavement	, ,	(ONK)	(ONK)	(ONK)	'
										Passenger	East	Turning Left	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201400052473 5/26/2014 1:45 PM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69										
3/20/2014 1.43 FWI	Clear	Diy	U	U	U	U	running	Daylight	40.09	Passenger	West	_Turning Left	Motor	Intersectio	(UNK)	(UNK)	(LINK)	(UNK)	١ 1
													Vehicle In Traffic	n				4 0141()	
										Passenger	South	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	2
201400317287 6/1/2014 4:55 PM	Clear	Dry	0	0	0	0	Sideswipe Same Direction	Daylight	46.69										
										Passenger	Northwest	Changing Lanes	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										Van/Mini-Van	West	Straight Ahead	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2

Report Produced : 11/6/2015 9:09 AM

By: CENTRAL\ADAMSCH

Page: 3 of 6

Collision Diagram

1/1/2014 to 12/31/2014

Date	Weather	Roadway	Α	Injuries B	<u></u>	Killed	Type of Crash	Light Condition	Mile	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201400054588 6/1/2014 6:25 PM	Clear	Dry	0	1	0	0	Turning	Daylight	46.69										
										Passenger	North	Turning Left	Vehicle	Intersectio n	(UNK) (UNK	(UNK)	(UNK)	1
										Pickup	West	Straight Ahead	In Traffic Motor Vehicle In Traffic	Intersectio n	(UNK)) (UNK	(UNK)	(UNK)	, 2
201400324786																			
6/4/2014 6:51 PM	Clear	Dry	0	0		0	Rear End	Daylight	46.69										
										Passenger	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)) (UNK) (UNK)	(UNK)	1
										SUV	North	Slow/Stop In Traffic	Motor Vehicle	On Pavement (Roadway)	(UNK)) (UNK) (UNK)	(UNK)	2
201400094591																			
7/2/2014 5:27 PM	Rain	Wet	0	0	0	0	Rear End	Daylight	46.69										
										Passenger	East	Backing	Motor Vehicle	On Pavement (Roadway)	(UNK) (UNK	(UNK)	(UNK)	, 1
										Bus Over 15 Passengers	East	Slow/Stop In Traffic	Motor Vehicle	On Pavement (Roadway)	(UNK)) (UNK) (UNK)	(UNK)	2
201400364784																			
8/3/2014 7:30 PM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69										
										- su ∀	South	Turning Left			(UNK	(UNK	(UNK)	(UNK)) 1
										Pickup	South	Turning Left		Pavement (Roadway) On	(UNK) (UNK) (UNK)	(UNK)) 2
												3	Vehicle	Pavement (Roadway)	(-	, (=	, (- ,	(- ,	
201400403873 9/29/2014 10:14 PM	Clear	Dry	0	0	0	0	Turning	Darkness	46.69										
										Passenger	South	Turning Left	Motor Vehicle	On Pavement	(UNK) (UNK	(UNK)	(UNK)) 1
										Van/Mini-Van	North	Straight Ahead	In Traffic Motor Vehicle	(Roadway) On Pavement (Roadway)	(UNK)) (UNK) (UNK)	(UNK)	1 2
201400269618													iii iiaiilo	(i (Oadway)					
10/24/2014 10:53 AM	Clear	Dry	0	1	0	0	Turning	Daylight	46.69										
										Passenger	North	Turning Left	Motor Vehicle	Intersectio	(UNK) (UNK	(UNK)	(UNK)) 1
													In Traffic						

Report Produced : 11/6/2015 9:09 AM

By: CENTRAL\ADAMSCH

Page : 4 of 6

Collision Diagram

1/1/2014 to 12/31/2014

Date	Weather	Roadway	Α	Injuries B		Killed	Type of Crash	Light Condition	Mile	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
										Passenger	West	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	2
201400318863 12/5/2014 10:52 AM	Cloudy/Overcast	Dry	0	1	1	0	Rear End	Daylight	46.69										
										Passenger	South	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										Truck Single Unit	South	Slow/Stop In Traffic	In Traffic Motor Vehicle	(Roadway) On Pavement (Roadway)	Motor Vehicle In	On Pavemen	(UNK)	(UNK)	2
										Passenger	South	Slow/Stop In Traffic	Motor Vehicle	On Pavement	Traffic Motor	(Roadwa y) On Pavemen	(UNK)	(UNK)	3
										Passenger	South	Slow/Stop In Traffic	Motor Vehicle	(Roadway) On Pavement	Vehicle In Traffic	t	(UNK)	(UNK)	4
201400332660														(Roadway)	(UNK)				
12/15/2014 3:30 PM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69					(redundy)					
										SUV	East	Turning Left				(UNK)	(UNK)	(UNK)	1
										Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic Motor	On	(UNK)	(UNK)	(UNK)	(UNK)	2
201400461420													Vehicle In Traffic	Pavement (Roadway)					
12720/2014 10:47 AT	r Clear	Dry	o	σ			Turning	Daylight	46.69										
										Van/Mini-Van	North	Turning Left				(UNK)	(UNK)	(UNK)	1
										Passenger	South	Other	Motor Vehicle In Traffic		(UNK)	(UNK)	(UNK)	(UNK)	2
201400346458	Glasse						- Poor-Fast	Powieki	_46-68_				Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)				
-12/00/2014 0:00 Am	Oloui	<i>5</i> ,					Treat End	Bayngri		Tractor With Semi-Trailer	East	Straight Ahead				(UNK)	(UNK)	(UNK)	1
										Van/Mini-Van	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
													Motor Vehicle In Traffic	On Pavement	(UNK)				

Report Produced : 11/6/2015 9:09 AM

By: CENTRAL\ADAMSCH

Page : 5 of 6

Collision Diagram

1/1/2014 to 12/31/2014

	TOTAL CRASHES	FAT/ CRASHE			B INJURY CRASHES	C INJ CRAS		PROPERTY DAMAGE CRASHES	TOTAL KILLED	TO		A INJURIES	B INJURIES	C INJURI	ES
	<u>20</u>		<u>0</u>	<u>0</u>	<u>3</u>		<u>3</u>	<u>14</u>	<u>0</u>		<u>7</u>	<u>0</u>	<u>3</u>		<u>4</u>
Туре	of Crash	Total	%	Dayof Wk		Total	%	Hour of Day		Total	%		Vehicle Type	Total	%
Rear E	End	9	45.0%	Monday		5	25.0%	09 AM		1	5.0%	Bus	Over 15 Passengers	1	2.3%
Sides	wipe Same Direction	1	5.0%	Tuesday		2	10.0%	10 AM		3	15.0%	Pass	enger	26	59.1%
Turnin	g	10	50.0%	Wednesday		3	15.0%	Noon		1	5.0%	Picku	qu	3	6.8%
TOTA	L:	20		Thursday		1	5.0%	1 PM		1	5.0%	SUV		5	11.4%
				Friday		2	10.0%	2 PM		3	15.0%	Tract	tor With Semi-Trailer	1	2.3%
				Saturday		4	20.0%	3 PM		2	10.0%	Truck	k Single Unit	3	6.8%
				Sunday		3	15.0%	4 PM		1	5.0%	Unkn	nown	1	2.3%
				TOTAL:		20		5 PM		1	5.0%	Van/l	Mini-Van	4	9.1%
								6 PM		3	15.0%	тот	AL:	44	
								7 PM		3	15.0%				
								10 PM		1	5.0%				
								TOTAL:		20					
Weatl	ner Cond	Total	%	Light Cond		Total	%	Road Surfac	9	Total	%	DIRF		Total	%
Clear		17	85.0%	Darkness		1	5.0%	Dry		15	75.0%	East		11	25.0%
Cloud	y/Overcast	1	5.0%	Darkness/ L	ighted Road	2	10.0%	Snow or Slus	n	2	10.0%	North	n	11	25.0%
Rain		1	5.0%	Daylight		17	85.0%	Wet		3	15.0%	North	nwest	1	2.3%
Snow		1	5.0%	TOTAL:		20		TOTAL:		20		South	h	15	34.1%
TOTA	L:	20										West	t	6	13.6%
												тот	AL:	44	

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 12/2/2014 10:44 AM

By: CENTRAL\SPERRYSJ

Page: 1 of 8

Collision Diagram

1/1/2013 to 12/31/2013

Date	Weather	Roadway	Α	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201301027356 1/12/2013 4:45 PM	Clear	Dry	0	0	0	0	Rear End	Dusk	46.69										
										Pickup	South	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	, 1
										SUV	South	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	. 2
201301110703																			
2/9/2013 2:24 PM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69	Passenger	Northwest	Turning Left	Motor	Intersectio	(UNK)		(UNK)	(UNK)	۱ 1
										. accongo		running zon	Vehicle In Traffic	n	(0.1.1)	(0.111)	(0.1.1)	(0.1.1)	·
										Passenger	South	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	2
201301151094 3/2/2013 4:16 AM	Unknown	Unknown	0	0	0	0	Angle	Darkness/ Lighted											
								-Road		SUV	West	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										SUV	North	Straight Ahead	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201301169788 3/12/2013 7:30 PM	Clear	Dry	0	0	0	0	Rear End	Darkness/ Lighted Road	46.69					, ,,					
										Unknown	North	Straight Ahead	Motor Venicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1_
										Passenger	North	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	, 2
201301182550 3/30/2013 11:15 PM	Clear	Dry	0	0	0	0	Rear End	Darkness/ Lighted Road	46.69										
								Noau		SUV	West	Backing	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	, 1
										Passenger	West	Slow/Stop - Right Turn	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201301222807																			
5/27/2013 4:25 PM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69										
										Passenger	South	Turning Left	Vehicle	Intersectio n	(UNK)	(- ,	(UNK)	(- /	1



Report Produced : 12/2/2014 10:44 AM

By: CENTRAL\SPERRYSJ

Page : 2 of 8

Collision Diagram

1/1/2013 to 12/31/2013

Date	Weather	Roadway		Injuries B	C	Killed	Type of Crash	Light Condition	Mile	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
										Van/Mini-Van	North	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK) 2
201301233025 6/10/2013 3:06 PM	Clear	Dry	0	0	0	0	Rear End	Daylight	46.69										
										Passenger	South	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK) 1
										Passenger	South	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 2
201301243115																			
6/21/2013 12:30 PM	Rain	Wet	0	0	0	0	Rear End	Daylight	46.69										
										Pickup	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 1
										SUV	West	Slow/Stop - Right Turn	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK	2
201301093226																			
6/30/2013 12:00 PM	Clear	Dry	0	0	0	0	Rear End	Daylight	46.69										
										Van/Mini-Van	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 1
										Passenger	North	Slow/Stop In Traffic	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 2
201301166959 8/26/2013 11:00 PM	Clear	Dry	0	0	5	0	Rear End	Darkness/ Lighted Road	46.69										
										Pickup	North	Other	Motor Vehicle	On Pavement	(UNK	(UNK)	(UNK)	(UNK)2
										Passenger	North	Other	In Traffic Motor Vehicle	(Roadway) On Pavement	, ,	(UNK)	(UNK)	(UNK) 3
										Truck Single Unit	North	Straight Ahead	In Traffic Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK) 1
										Van/Mini-Van	North	Other	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 4
201301320107 9/6/2013 8:00 PM	Clear	Dry	0	0	0	0	Rear End	Darkness/ Lighted Road	46.69	Passenger	South	Straight	Motor	On	(UNK	(UNK)	(UNK)	(UNK) 1
										i asseriger	Journ	Ahead	Vehicle In Traffic	Pavement	ν- ,	(ONK)	(ONK)	(OIVIN	'

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 12/2/2014 10:44 AM

By: CENTRAL\SPERRYSJ

Page : 3 of 8

Collision Diagram

1/1/2013 to 12/31/2013

Date	Weather	Roadway	Α	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
										Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 2
201301354166 10/5/2013 7:09 AM	Clear	Dry	0	0	0	0	Fixed Object	Daylight	46.69										
										Pickup	South	Skidding/Co ntrol Loss		Pavement	Other Fixed	Off I	Hit Parked Vehicle	Othe	r 1
										Passenger	Southeast	Parked	Motor Vehicle In Traffic	- Right Other	Object (UNK)	t - Right (UNK)	(UNK)	(UNK) 2
201301358031 10/10/2013 5:46 PM	Clear	Dry	0	0	0	0	Rear End	Daylight	46.69										
										SUV	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 1
										Passenger	North	Slow/Stop In Traffic	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 2
- 201301365583 10/18/2013 2:48 PM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69										
										Passenger	South	Turning Right	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 1
										Passenger	East	Slow/Stop In Traffic	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 2
201301370694 10/21/2013 6:50 PM		Dry	0	0	0	0	Turning	Darkness/ Lighted Road	46.69										
								Nodu		Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 2
										Passenger	Northwest	Turning Left	Motor Vehicle	On (Pavedway)	(UNK)	(UNK)	(UNK)	(UNK) 1
201301370164 	-/3	-Dry				_σ	Rear End	-Dusk	46.69				III Hallic	Paverment)					
10/24/2013 0.40 PM	Clear	Ыу	U	U	U	U	Real Ellu	Dusk	40.09	Passenger	North	Starting In Traffic	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK) 1
										Pickup	North	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On (Roadway) Payement	(UNK)	(UNK)	(UNK)	(UNK) 2

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 12/2/2014 10:44 AM

By: CENTRAL\SPERRYSJ

Page: 4 of 8

Collision Diagram

1/1/2013 to 12/31/2013

Date	Weather	Roadway	Α	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201301371585 10/25/2013 2:30 PM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69										
										Pickup	West	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										Van/Mini-Van	East	Turning Left	In Traffic Motor Vehicle In Traffic	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	2
201301398923 44/28/2013 41-25 PM	-Glear						- Angle	- Đarkness/ Łighted	-46-69 -										
1720/2010 11:20 1 III	Oldai	Diy	Ü	Ü	Ü	Ü	, tigic	Road	40.00	Passenger	North	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)) 1
										Passenger	West	Straight Ahead	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)) 2
201301410579 12/7/2013 5:55 PM	Clear	Dry	0	0	0	0	Rear End	Dusk	46.69										
										Passenger	South	Straight Ahead	Motor Vehicle	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)) 1
										Passenger	South	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	, 2
201301413686 12/10/2013 9:30 AM	Clear	Wet	0	0	0	0	Turning	Daylight	46.69										
										Unknown	West	Unknown	Motor Venicle	On Pavement	(UNK)	(UNK	(UNK)	(UNK)) 1
										Van/Mini-Van	West	Turning Right	In Traffic Motor Vehicle	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	, 2
201301419313 12/15/2013 7:34 PM	Clear	Snow or	0	0	1	0	Turning	Darkness/ Lighted	46.69										
		Slush						Road		SUV	Northwest	Turning Left	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	, 1
										Passenger	South	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)) 2
201301419570 12/16/2013 3:30 PM	Snow	Snow or Slush	0	0	0	0	Rear End	Daylight	46.69										
		Siusii								Passenger	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 12/2/2014 10:44 AM

By: CENTRAL\SPERRYSJ

Page : 5 of 8

Collision Diagram

1/1/2013 to 12/31/2013

Date	Weather	Roadway	Α	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
										SUV	North	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201301424733 12/21/2013 8:45 AM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69										
										Passenger	Northeast	Turning Right	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										SUV	Northeast	Unknown	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2

Report Produced: 12/2/2014 10:44 AM

By: CENTRAL\SPERRYSJ

Page : 6 of 8

Collision Diagram

1/1/2013 to 12/31/2013

TOTAL CRASHES	FAT/ CRASHE	AL AIN	NJURY BINJUR ASHES CRASHE	Y CIN S CRA	IJURY SHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED		OTAL JRED	A INJURIES	B INJURIES	C INJUR	RIES
<u>23</u>		<u>0</u>	<u>0</u>	0	<u>2</u>	<u>21</u>	<u>0</u>		<u>6</u>	<u>0</u>	<u>0</u>		<u>6</u>
Type of Crash	Total	%	Dayof Wk	Total	%	Hour of Day		Total	%		Vehicle Type	Total	%
Angle	2	8.7%	Monday	5	21.7%	04 AM		1	4.3%	Pass	enger	25	52.1%
Fixed Object	1	4.3%	Tuesday	2	8.7%	07 AM		1	4.3%	Picku	р	6	12.5%
Rear End	12	52.2%	Thursday	3	13.0%	08 AM		1	4.3%	SUV		9	18.8%
Turning	8	34.8%	Friday	4	17.4%	09 AM		1	4.3%	Truck	Single Unit	1	2.1%
TOTAL:	23		Saturday	7	30.4%	Noon		2	8.7%	Unkn	own	2	4.2%
			Sunday	2	8.7%	2 PM		3	13.0%	% Van/I	Mini-Van	5	10.4%
			TOTAL:	23		3 PM		2	8.7%	тот	AL:	48	
						4 PM		2	8.7%				
						5 PM		2	8.7%				
						6 PM		2	8.7%				
						7 PM		2	8.7%				
						8 PM		1	4.3%				
						11 PM		3	13.0%	6			
						TOTAL:		23					
Weather Cond	Total	%	Light Cond	Total	%	Road Surface	e	Total	%	DIRF		Total	%
Clear	20	37.0%	Darkness/ Lighted Road	8	34.8%	b Dry		18	78.3%	6 East		2	4.2%
Rain	1	4.3%	Daylight	12	52.2%	Snow or Slush	n	2	8.7%	North	ı	17	35.4%
Snow	1	4.3%	Dusk	3	13.0%	. Unknown		1	4.3%	North	east	2	4.2%
Unknown	1	4.3%	TOTAL:	23		Wet		2	8.7%	North	west	3	6.3%
TOTAL:	23					TOTAL:		23		South	1	14	29.2%

Illinois Department of Transportation Division of Traffic Safety

Report Produced : 10/29/2013 10:42 AM

By: CENTRAL\ADAMSCH

Page: 1 of 9

Collision Diagram

1/1/2012 to 12/31/2012

Date	Weather	Roadway	A	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehiele Type	DIRP	Maneuver	Event 1	Loe 1	Event 2	Loe 2	Event 3	Loe 3	Unit
201201042109 1/11/2012 3:50 PM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69		_								
										Passenger	East	Turning Left	Motor Vehicle In Traffic	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										SUV	West	Straight Ahead	Motor Vehicle	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201201050107 1/28/2012 6:10 AM	-Clear	-Wet			0	0	-Rear End	Darkness, Lighted	46.69 –										
								Road		Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
										Passenger	South	Slow/Stop In Traffic	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	2
201201087073 3/4/2012 10:42 PM	Clear	Dry	0	1	0	0	Rear End	Darkness, Lighted	46.69										
								-Road		Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
										SUV	East	Slow/Stop In Traffic	Motor venicle In Traffic	On Pavement	Overturn	Pavemen t	(- ,	(UNK)	2
																(Roadwa y)			
201201132846 3/20/2012 8:40 AM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69										
										Tractor With Semi	North	Turning Right	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										Passenger	North	Turning Right	In Traffic Motor Vehicle	(Roadway) On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	2
201201162567 3/29/2012 6:35 AM	Clear	Dry	0	0	0	0	Rear End	Daylight	46.69										
										Passenger	East	Slow/Stop In Traffic	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
										Passenger	East	Slow/Stop In Traffic	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	2

Illinois Department of Transportation Division of Traffic Safety

Report Produced: 10/29/2013 10:42 AM

By: CENTRAL\ADAMSCH

Page: 2 of 9

Collision Diagram

1/1/2012 to 12/31/2012

Date	Weather	Roadway	Α	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehiele Type	DIRP	Maneuver	Event 1	Loe 1	Event 2	Loe 2	Event 3	Loe 3	Unit
201201190329 4/21/2012 1:00 PM	Clear	Dry	0	0	0	0	Sideswipe Same Direction	Daylight	46.69										
							Direction			SUV	East	Changing Lanes	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK) 1
										Passenger	East	Straight Ahead	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 2
201201205198 5/44/2012 12:23-AM-		Hakaewn	-0		-0		-Rear End	Darkness-Lighted	- 46-60- -										
								Road		SUV	East	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK) 1
										SUV	East	Straight Ahead	In Traffic Motor Vehicle	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 2
201201130931													III TTAIIIC	(Noadway)					
5/26/2012 3:50 PM	Clear	Dry	0	1	0	0	Pedalcyclist	Daylight	46.69										
										Passenger	West	Turning Right	Pedalcycl ist	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK) 1
201201218680 5/31/2012 5:00 PM	Rain	Wet	0	0	0	0	Turning	Daylight	46.69										
										SUV	Southwest	Turning Left	Motor	Other	(<u>UNK)</u>	(ŪNK)	(ŪÑK)	(ŪNK)—- ₁
										Passenger	East	Straight Ahead	Vehicle In Traffic Motor Vehicle In Traffic	Other	(UNK)	(UNK)	(UNK)	(UNK) 2
201201133315 5/31/2012 9:30 PM	Rain	Wet	0	0	1	0	Rear End	Darkness, Lighted Road	46.69				III TIAIIIC						
								Noau		Passenger	East	Straight Ahead	Motor	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)1
										Passenger	East	Slow/Stop In Traffic	In Traffic Motor Vehicle		(UNK)	(UNK)	(UNK)	(UNK) 2
201201161326 6/4/2012 10:20 AM	Clear	Dry	0	0	1	0	Turning	Daylight	46.69										
										SUV	North	Turning Left	Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK) 1
										Tractor With Semi -Trailer	South	Straight Ahead	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 2

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 10/29/2013 10:42 AM

By: CENTRAL\ADAMSCH

Page: 3 of 9

Collision Diagram

1/1/2012 to 12/31/2012

Passenger Southwest Turning Left Vehicle Payment In Traffic (Roadway) 201201252425 7/1/2012 1:17 PM Rain Wet 0 0 1 0 Rear End Daylight 46.89 Passenger East Straight Ahead Note of Neincle Payment In Traffic (Roadway) Passenger East Straight Ahead Note of Neincle Payment In Traffic (Roadway) 10 Traffic Roadway) Passenger East Straight Ahead Note of Neincle Payment In Traffic (Roadway) 10 Traffic Roadway) 11 Traffic Roadway) 11 Traffic Roadway) 11 Traffic Roadway) 12 Traffic Roadway) 13 Traffic Roadway) 14 Roadway 15 Traffic Roadway) 15 Traffic Roadway) 16 Traffic Roadway) 17 Traffic Roadway) 18 Traffic Roadway)	Date	Weather	Roadway	A	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehiele Type	DIRP	Maneuver	Event 1	Loe 1	Event 2	Loe 2	Event 3	Loe 3	Unit
Passenger Southwest Turning Left (Roadway) 201201252425 7/1/2012 1:17 PM Rain Wet 0 0 1 0 Rear End Daylight 46.69 Passenger East Straight Annead Vehicle Roadway) Passenger East Straight Name of Vehicle Pavement In Traffic (Roadway) In Traffic (Roadway) UNK) (UNK) (UNK) (UNK) Passenger East Straight More On Vehicle Pavement In Traffic (Roadway) Pickup East Straing In More Vehicle Pavement In Traffic (Roadway) In Traffic In Traffic (Roadway) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) Passenger South Straight More Vehicle Pavement In Traffic (Roadway) In Traffic (Roadway) In Traffic (Roadway) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) (UNK)		Clear	Dry	0	0	0	0	Turning	Dusk	46.69										
Passenger Southwest Turning Left Motor Vehicle Paswment (Roadway) Control											Passenger	East	Straight Ahead	Vehicle	Pavement	, ,) (UNK)	(UNK	(UNK) 1
7/1/2012 1:17 PM Rain Wet 0 0 1 0 Rear End Daylight 46.69 Passenger East Straight Vehicle In Traffic Roadway) 201201348594 9/5/2012 1:220 PM Clear Dry 0 0 0 Turning Daylight 46.69 SUV West Turning Left Motor In Traffic Passenger South Straight Wotor On (UNK) (U											Passenger	Southwest	Turning Left	Motor Vehicle	On Pavement	(UNK) (UNK)	(UNK	(UNK) 2
Passenger East Straight Ahead Vehicle Pavement (UNK) (
Name	7/1/2012 1:17 PM	Rain	Wet	0	0	1	0	Rear End	Daylight	46.69	Passenger	East	Straight		On Boyoment	(UNK) (UNK)) (UNK	(UNK) 1
9/5/2012-12:20 PM. Clear											Passenger	East	Slow/Stop	In Traffic Motor Vehicle	(Roadway) On Pavement	(UNK)) (UNK)) (UNK	(UNK) 2
Pickup East Starting In Motor Vehicle Pavement (Roadway) Pickup East Stow/Stop Motor In Traffic (Roadway) Pickup East Stow/Stop Motor In Traffic (Roadway) Pickup East Stow/Stop Motor In Traffic (Roadway) Pickup East Starting In Motor Vehicle Pavement (Roadway) Passenger South Straight Motor Intersectio (UNK) (UNK) (UNK) Passenger South Straight Motor Don (UNK) (UNK) (UNK) Passenger South Straight Motor Pavement Pavement Roadway) Passenger South Straight Motor Pavement Roadway)																				
Pickup East Slow/Stop Notor On (UNK) (UNK) (UNK)	9/5/2012_12:20 PM	Clear	Dry	0		0	0	Rear End	Daylight	_46.69_										
201201349409 9/6/2012 9:52 AM Clear Dry 0 0 0 Turning Daylight 46.69 SUV West Turning Left Motor Intersectio (UNK) (UNK											Pickup	East	Starting In Traffic	Vehicle	Pavement	` ') (UNK)) (UNK	(UNK) 1
9/6/2012 9:52 AM Clear Dry 0 0 0 Turning Daylight 46.69 SUV West Turning Left Motor Vehicle n In Traffic Notor Intersectio (UNK) (U											Pickup	East	Slow/Stop In Traffic	Motor Vehicle	On Pavement	(UNK) (UNK)) (UNK	(UNK) 2
SUV West Turning Left Motor Intersectio (UNK) (U			_																	
Vehicle n In Traffic Passenger South Straight Motor Intersectio (UNK) (UNK) (UNK) (UNK) Ahead Vehicle n In Traffic 201201350297 9/7/2012 6:50 PM Clear Dry 0 0 0 Rear End Darkness, Lighted 46.69 Road Passenger South Straight Motor On (UNK) (UNK) (UNK) (UNK) (UNK) (UNK) Passenger South Straight Motor On (UNK) (UNK) (UNK) (UNK) (UNK) (UNK)	9/6/2012 9:52 AM 	Clear	Dry	0	0	0	0 	Turning	Daylight	46.69										
Passenger South Straight Motor Intersectio (UNK)											SUV	West	Turning Left	Vehicle		(UNK)) (UNK)) (UNK	(UNK) 1
9/7/2012 6:50 PM Clear Dry 0 0 0 Rear End Darkness, Lighted 46.69 Road Passenger South Straight Wotor On (UNK) (UNK) (UNK) In Traffic (Roadway)											Passenger	South	Straight Ahead	Motor Vehicle		(UNK)) (UNK)	(UNK	(UNK) 2
Ahead Venicle Pavement In Traffic (Roadway)		Clear	Dry	0	0	0	0	Rear End		I 46.69	Doggonger	South	Stroight	Motor	On	/LINIZ) (LINIZ)	A /LINIZ)(UNK	\ 1
Passenger South Slow/Stop Motor On ´´ (UNK) (UNK) (UNK) In Traffic Vehicle Pavement												South	Slow/Stop	In Traffic Motor	(Roadway) On					

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 10/29/2013 10:42 AM

By: CENTRAL\ADAMSCH

Page: 4 of 9

Collision Diagram

1/1/2012 to 12/31/2012

Date	Weather	Roadway	A	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehiele Type	DIRP	Maneuver	Event 1	Loe 1	Event 2	Loe 2	Event 3	Loe 3	Unit
201201353522 9/11/2012 7:35 PM	Clear	Dry	0	0	1	0	Rear End	Darkness, Lighted Road	46.69										
										Passenger	South	Starting In Traffic	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										Passenger	South	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201201374076																			
10/5/2012 3:37 PM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69										
										SUV	East	Turning Left	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)) 1
										Passenger	North	Turning Left		Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	2
201201375967																			
10/8/2012 7:30 PM	Clear	Dry	0	0	0	0	Rear End	Darkness	46.69										
										Passenger	North	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										SUV	North	Straight Ahead	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201201381268 10/14/2012 4:30 AM	Rain	Wet	0	0	0	0	Rear End	Darkness, Lighted Road	46.69						4.0.0		4 11 11 6		
										Passenger	South	Straight Ahead	Vehicle	Pavement	(- /	(UNK)	(014K)	(UNK)	 1
										Passenger	South	Slow/Stop In Traffic	Motor Vehicle	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201201380739 10/14/2012 4:30 PM	Deia	10/-1		0		•	Townsia a	Day Bake	40.00										
110/14/2012 4:30 PM	Rain	Wet	0	0	0	0	Turning	Daylight	46.69	Passenger	East	Turning Left		On	(UNK)	(UNK)	(UNK)	(UNK)	1
										Passenger	North	Straight Ahead	In Traffic Motor Vehicle	Pavement (Roadway) On Pavement (Roadway)	(UNK)			` <i>-</i>	

Report No : SDM-RC002

Sorted by : Mile / Date / ICN

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 10/29/2013 10:42 AM

By: CENTRAL\ADAMSCH

Page : 5 of 9

Collision Diagram

1/1/2012 to 12/31/2012

Date	Weather	Roadway	A	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehiele Type	DIRP	Maneuver	Event 1	Loe 1	Event 2	Loe 2	Event 3	Loe 3	Unit
201201382165 10/16/2012 7:10 PM	Clear	Dry	0	0	0	0	Sideswipe Same Direction	Darkness, Lighted Road	46.69										
							Direction	Noad		Unknown	West	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										Passenger	West	Straight Ahead	In Traffic Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	2
										SUV	West	Straight Ahead	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201201383556 10/17/2012 9:55 PM	Rain	Wet	0	22	0	0	Pedestrian	Darkness, Lighted	46.69										
								Road		Passenger	South	Straight Ahead	Pedestria n	Intersectio n	Pedestrian	Intersecti on	, ,	(UNK)	1
201201400989 11/8/2012 3:23 PM	Clear	Dry	0	0	0	0	Rear End	Daylight	46.69										
1101201201201111	Cloui				<u>-</u>	<u>-</u>	rodi Ella	Dayligit	40.00	Passenger	North	Backing	Motor Vehicle	Intersectio n	(UNK)	(UNK)		(UNK)	1
										SUV	North	Straight Ahead	In Traffic Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	2
201201407733	Olasar	D	0	0		0	Dani Frad	Deciliate	40.00										
11/16/2012 9:57 AM	Clear	Dry		0	0		Rear End	Daylight	46.69	Passenger	-South	Straight		-On	41NK	(UNK)	⊢−−-(UNK)	(UNK)	1
										3		Ahead	Vehicle In Traffic	Pavement (Roadway)	(- ,	(- ,	(- ,	(-)	
201201332303										SUV	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
	Clear	Wet	0	0	0	0	Rear End	Daylight	46.69										
										Passenger	South	Unknown	Motor Vehicle	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	1
										Tractor With Semi -Trailer	South	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	2
201201422486 12/8/2012 5:30 PM	Clear	Dry	0	0	0	0	Turning	Darkness, Lighted Road	46.69	CUIV	Nowthoos	Tunning 1 - ft	Matar	0.5	(1 Jan 12)	(11842)		(11842)	
										SUV	Northeast	Turning Left	Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1

Report No : SDM-RC002

Sorted by : Mile / Date / ICN

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 10/29/2013 10:42 AM

By: CENTRAL\ADAMSCH

Page: 6 of 9

Collision Diagram

1/1/2012 to 12/31/2012

Date	Weather	Roadway	A	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehiele Type	DIRP	Maneuver	Event 1	Loe 1	Event 2	Loe 2	Event 3	Loe 3	Unit
										Van/Mini-Van	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)) (UNK)	(UNK)	(UNK	() 2
2 01201343901 12/13/2012 10:28 PM	l Clear	Dry	0	0	0	0	Rear End	Darkness, Lighted Road	46.69										
										Passenger	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)) (UNK)	(UNK)	(UNK	.) 1
										Van/Mını-Van	North	Straight Ahead	Motor Vehicle	On Pavement (Roadway)	(UNK)) (UNK)	(UNK)	(UNK	.) 2
201201427506																			
12/15/2012 6:40 AM	Rain	₩et	σ	0		σ	Turning	Dawn	46.69										
										Passenger	Northwest	Turning Right	Motor Vehicle	On Pavement	(UNK)) (UNK)	(UNK)	(UNK	.) 1
										Passenger	North	Straight Ahead	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)) (UNK)	(UNK)	(UNK	() 2
201201331724 12/18/2012 5:55 PM	Clear	Dry	0	0	0	0	Rear End	Darkness, Lighted	46.69										
								Road		Passenger	West	Straight Ahead	Motor Vehicle	On Pavement	(UNK)) (UNK)	(UNK)	(UNK	.) 1
										Tractor Without Semi-Trailer	West	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)) (UNK)	(UNK)	(UNK	3) 2
201201434718 12/22/2012 7:30 PM	Clear	Dry	0	0	0	0	Rear End	Darkness, Lighted Road	46.69										
										_\$UV	South	Straight Ahead	Motor Vehicle In Traffic	Pavement (Roadway)	(UNK))(UNK)	(UNK)	(UNK) 1
										Passenger	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement	(UNK)) (UNK)	(UNK)	(UNK	3) 2

Report Produced : 10/29/2013 10:42 AM

By: CENTRAL\ADAMSCH

Page: 7 of 9

Collision Diagram

1/1/2012 to 12/31/2012

TOTAL CRASHES	FA [·] CRASH	TAL A IES CR	INJURY RASHES	B INJURY CRASHES	C INC		PROPERTY DAMAGE CRASHES	TOTAL KILLED	T(INJU	OTAL JRED	A INJURIES	B INJURIES	C INJUR	RIES
<u>31</u>		<u>C</u>	<u>0</u>	<u>3</u>		<u>4</u>	<u>24</u>	<u>0</u>		<u>8</u>	<u>0</u>	<u>4</u>		<u>4</u>
Type of Crash	Total	%	Dayof Wk		Total	%	Hour of Day		Total	%		Vehicle Type	Total	%
Pedalcyclist	1	3.2%	Monday		2	6.5%	Midnight		1	3.2%	Pass	enger	37	60.7%
Pedestrian	1	3.2%	Tuesday		5	16.1%	04 AM		1	3.2%	Picku	p	2	3.3%
Rear End	17	54.8%	Wednesda	ıy	4	12.9%	06 AM		3	9.7%	SUV		15	24.6%
Sideswipe Same Direction	2	6.5%	Thursday		6	19.4%	07 AM		1	3.2%	Tracte	or With Semi-Trailer	3	4.9%
Turning	10	32.3%	Friday		4	12.9%	08 AM		1	3.2%	Tract	or Without Semi-Trailer	1	1.6%
TOTAL:	31		Saturday		6	19.4%	09 AM		2	6.5%	Unkn	own	1	1.6%
			Sunday		4	12.9%	10 AM		1	3.2%	Van/N	Mini-Van	2	3.3%
			TOTAL:		31		Noon		1	3.2%	тот	AL:	61	
							1 PM		2	6.5%				
							3 PM		4	12.9%	Ď			
							4 PM		1	3.2%				
							5 PM		3	9.7%				
							6 PM		1	3.2%				
							7 PM		4	12.9%	, b			
							8 PM		1	3.2%				
							9 PM		2	6.5%				
							10 PM		2	6.5%				
							TOTAL:		31					
Weather Cond	Total	%	Light Con	nd	Total	%	Road Surface		Total	%	DIRP	ı	Total	%
Clear	24	77.4%	Darkness		1	3.2%	Dry		21	67.7%			19	31.1%

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 10/29/2013 10:44 AM

By: CENTRAL\ADAMSCH

Page : 1 of 8

Collision Diagram

1/1/2011 to 12/31/2011

Date	Weather	Roadway	A	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehiele Type	DIRP	Maneuver	Event 1	Loe 1	Event 2	Loe 2	Event 3	Loe 3	Unit
201101033872 1/3/2011 6:30 AM	Clear	Dry	0	0	0	0	Rear End	Dusk	46.69										
										SUV	North	Slow/Stop In Traffic	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
201101049625										SUV	North	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
1/18/2011 1:45 PM =	-Snow				0	0	-Turning	-Daylight	46.69										
		Slush								Other	Northwest	Turning Right	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										Other	Northwest	Turning Right	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201101080768 2/2/2011 2:00 PM	Snow	Snow or	0	0	0	0	Turning	Daylight	46.69										
		Slush								Pickup	East	Turning Right	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
201101073434										SUV	East	Straight Ahead	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
2/27/2011 4:30 AM	Clear	Unknown	0	0	0	0	Rear End	Darkness, Lighted Road	46.69										
										Passenger	North	Changing Lanes		On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
004404440040										Passenger	North	Straight Ahead	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201101110313 3/6/2011 2:15 PM	Clear	Dry	0	0	0	0	Rear End	Daylight	46.69										
										Passenger	West	Straight Ahead	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
						- 			- 	SUV	West	Slow/Stop In Traffic	Motor Vehicle	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 10/29/2013 10:44 AM

By: CENTRAL\ADAMSCH

Page: 2 of 8

Collision Diagram

1/1/2011 to 12/31/2011

Date	Weather	Roadway	A	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehiele Type	DIRP	Maneuver	Event 1	Loe 1	Event 2	Loe 2	Event 3	Loe 3	Unit
201101103347 3/8/2011 7:48 PM	Clear	Dry	0	0	0	0	Rear End	Darkness, Lighted Road	46.69										
										SUV	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
										Passenger	North	Slow/Stop In Traffic	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	2
										Passenger	North	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201101130108		_D=					_Ando	Davlight	46-60										
47142011 4.00 1 III	Olean	Diy	2	Ü	Ü	Ü	Angle	Dayligin	40.03	Passenger	East	Other	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	1
										Passenger	Unknown	Other	In Traffic Motor Vehicle	(Roadway) On Pavement	(UNK)	(UNK)	(UNK)	(UNK)	2
										Passenger	North	Other	In Traffic Motor Vehicle	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201101194156													III II allic	(Itoauway)					ļ
5/1/2011 3:50 PM	Clear	Dry	0	0	1	0	Rear End	Daylight	46.69					-on					4
										Passenger	East	Straight Ahead	Motor Vehicle In Traffic	Pavement (Roadway)	(UNK)	, ,	, ,	` ,	
										Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201101152890 5/4/2011 12:30 PM	Unknown	Dry	0	0	0	0	Rear End	Unknown	46.69										ļ
										Passenger	East	Straight	Motor	On Rayement	(UNK)	(UNK)	(UNK)	(UNK)	1
										Passenger	East	Slow/Stop In Traffic	In Traffic Motor Vehicle	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201101194843 5/14/2011 6:44 AM	Clear	Dry	0	1	0	0	Rear End	Daylight	46.69										
										Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 10/29/2013 10:44 AM

By: CENTRAL\ADAMSCH

Page: 3 of 8

Collision Diagram

1/1/2011 to 12/31/2011

Date	Weather	Roadway	A	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehiele Type	DIRP	Maneuver	Event 1	Loe 1	Event 2	Loe 2	Event 3	Loe 3	Unit
										Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)) (UNK	(UNK	.) 2
2 01101174108 5/22/2011 3:50 AM	Clear	Dry	0	0	0	0	Rear End	Darkness, Lighted Road	46.69										
								Road		Passenger	East	Straight Ahead	Motor Vehicle	On Pavement	(UNK	(UNK)	(UNK	(UNK	.) 1
										Passenger	East	Straight Ahead	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK	(UNK)) (UNK	(UNK	.) 2
201101190569																			
6/9/2011 7:25 AM	Rain	Wet		0	-0		Turning	Daylight	46.69										
										Passenger	Unknown	Unknown	Motor Vehicle In Traffic	Intersectio n	(UNK	(UNK)) (UNK	(UNK) 1
										Passenger	Southeast	Turning Left		Intersectio n	(UNK)	(UNK)	(UNK	(UNK	2
201101201583																			
6/15/2011 2:15 PM	Rain	Wet	0	1	0	0	Turning	Daylight	46.69										
										Van/Mini-Van	Southeast	Turning Left	Vehicle	On Pavement	(UNK	(UNK)	(UNK	(UNK) 1
										Passenger	North	Straight Ahead	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)) (UNK)	(UNK	2
201101233756 6/19/2011 9:45 PM	Clear	Dry	0	0	1	0	Rear End	Darkness, Lighted Road	46.69										
										- Passenger	- -Eas t	Straight Ahead	Vehicle	Pavement	(UNK	(UNK)	(UNK)—— (UNK	}+-
										SUV	East	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK	(UNK)) (UNK	(UNK	.) 2
201101251047 7/12/2011 10:10 PM	Clear	Dry	0	0	0	0	Rear End	Darkness, Lighted	46.69										
								Road		SUV	East	Backing	Motor Vehicle	On Pavement	(UNK	(UNK)	(UNK	(UNK) 1
										Passenger	East	Slow/Stop In Traffic	In Traffic Motor Vehicle	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)) (UNK	(UNK	.) 2

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 10/29/2013 10:44 AM

By: CENTRAL\ADAMSCH

Page : 4 of 8

Collision Diagram

1/1/2011 to 12/31/2011

Date	Weather	Roadway	A	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehiele Type	DIRP	Maneuver	Event 1	Loe 1	Event 2	Loe 2	Event 3	Loe 3	Unit
201101258429 7/19/2011 10:18 AM	Clear	Dry	0	0	0	0	Rear End	Daylight	46.69										
										SUV	East	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK	(UNK) 1
										SUV	East	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK	(UNK) 2
201101269987																			
8/13/2011 6:00 PM	Rain	Wet	0	0	0	0	Rear End	Daylight	46.69										
										SUV	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement	(UNK)	(UNK)	(UNK	(UNK) 1
										Passenger	North	Straight Ahead	Motor Vehicle	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK	(UNK) 2
201101293687																			
8/18/2011 9:30 AM	_Clear	_Dry		0	-0	0	_Rear End	Daylight	_46_69_										
										SUV	South	Straight Ahead	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK	(UNK) 1
										SUV	South	Slow/Stop In Traffic	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK	(UNK) 2
201101346977 9/7/2011 8:17 PM	Clear	Dry	0	0	1	0	Rear End	Darkness, Lighted Road	46.69										
										Passenger	East	Straight Ahead	Motor Vehicle	On Pavement	(UNK	T(UNK)	טאגי	TUNK	5 1
										Passenger	East	Slow/Stop In Traffic	Motor Vehicle	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK	(UNK) 2
201101425029																			
11/18/2011 11:45 AM	Rain	Wet	0	0	2	0	Turning	Daylight	46.69										
										Passenger	South	Straight Ahead	Motor Vehicle	Intersectio n	(UNK	(UNK)	(UNK	(UNK	<u>1</u> 1
										Passenger	Northwest	Turning Left	In Traffic	Intersectio n	(UNK)	(UNK)	(UNK	(UNK) 2

Illinois Department of Transportation
Division of Traffic Safety

Report Produced : 10/29/2013 10:44 AM

By: CENTRAL\ADAMSCH

Page : 5 of 8

Collision Diagram

1/1/2011 to 12/31/2011

Date	Weather	Roadway	Α	Injuries B	С	Killed	Type of Crash	Light Condition	Mile	Vehiele Type	DIRP	Maneuver	Event 1	Loe 1	Event 2	Loe 2	Event 3	Loe 3	Unit
201101404542		_																	
11/23/2011 12:25 AM	Clear	Dry	0	0	0	0	Rear End	Daylight	46.69										
										Passenger	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement	(UNK)	(UNK)	(UNK)	(UNK) 1
										Passenger	North	Slow/Stop In Traffic	Motor Vehicle	(Roadway) On Pavement	(UNK)	(UNK)	(UNK)	(UNK	.) 2
201101442231													In Traffic	(Roadway)					
12/7/2011 12:15 PM	Clear	Dry	0	0	0	0	Turning	Daylight	46.69										ŀ
										Passenger	East	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK) 1
										SUV	Southwest	Turning Left	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK	2
201101443156													III TTAITIO						
12/26/2011 11:30 PM	Rain	Wet	0	0	0	0	Turning	Darkness, Lighted	46.69										
								Road		Van/Mini-Van	West	Turning Left	Motor Vehicle	On Pavement	(UNK)	(UNK)	(UNK)	(UNK) 1
										Passenger	East	Turning Right	In Traffic Motor Vehicle In Traffic	(Roadway) On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK) 2

Report Produced : 10/29/2013 10:44 AM

By: CENTRAL\ADAMSCH

Page : 6 of 8

Collision Diagram

1/1/2011 to 12/31/2011

	TOTAL CRASHES	FATAL CRASHES	A IN CRA	JURY SHES	B INJURY CRASHES	C INJU CRASI	JRY HES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TO INJUI	TAL RED	A INJURIES E	3 INJURIES	C INJURIE	S
	<u>23</u>	<u>0</u>		1	<u>2</u>		<u>4</u>	<u>16</u>	<u>0</u>		<u>9</u>	<u>2</u>	<u>2</u>		<u>5</u>
Тур	e of Crash	Total	%	Dayof W	'k	Total	%	Hour of Day		Total	%		Vehicle Type	e Total	%
Angl	е	1	4.3%	Monday		2	8.7%	Midnight		1	4.3%	Other		2	4.2%
Rea	r End	15	65.2%	Tuesday		4	17.4%	03 AM		1	4.3%	Passenç	ger	30	62.5%
Turn	ing	7	30.4%	Wedneso	lay	6	26.1%	04 AM		1	4.3%	Pickup		1	2.1%
тот	AL:	23		Thursday	,	3	13.0%	06 AM		2	8.7%	SUV		13	27.1%
				Friday		1	4.3%	07 AM		1	4.3%	Van/Min	ii-Van	2	4.2%
				Saturday		2	8.7%	09 AM		1	4.3%	TOTAL:	:	48	
				Sunday		5	21.7%	5 10 AM		1	4.3%				
				TOTAL:		23		11 AM		1	4.3%				
								Noon		2	8.7%				
								1 PM		1	4.3%				
								2 PM		3	13.0%	%			
								3 PM		1	4.3%				
								4 PM		1	4.3%				
								6 PM		1	4.3%				
								7 PM		1	4.3%				
								8 PM		1	4.3%				
								9 PM		1	4.3%				
								10 PM		1	4.3%				
								11 PM		1	4.3%				
								TOTAL:		23					

Traffic Volume

October 2013


The traffic numbers below were obtained from the IDOT website per the RLR Guideline document published by IDOT. Only ADT values were available, peak numbers were not provided.

Cicero Ave ADT

North: 43,700South: 42,900

79th St ADT

East: 28,900West: 29,400



October 2015


The traffic numbers below were obtained from the IDOT website per the RLR Guideline document published by IDOT. Only ADT values were available, peak numbers were not provided.

Cicero Ave ADT

North: 45,100South: 36,600

79th St ADT

East: 27,900West: 27,900



Summary

All processes are in compliance with the RLR regulations laid out by the Illinois Department of Transportation District 1 Bureau of Traffic Operations.

In 2014 **The City of Burbank** received approval from the Illinois Department of Transportation (IDOT) to install Red Light Running (RLR) cameras on the eastbound and southbound approaches at the intersection of 79th St and Cicero Ave. The installation followed a comprehensive analysis and justification process. Due to a field change submitted on 5/08/2015, the live date of the eastbound camera was delayed. Pending a timely receipt of IDOT crash data, a report pertaining to the eastbound approach of this intersection will be available in 2017. The dates of the most relevant events are listed below.

- Date at which the justification report was submitted: 12/24/2013 approved: 2/20/2014
- Submitted for installation: 4/25/2014 approved: 6/23/2014
- Date at which the permit and bond was submitted: 8/04/2014 and approved: 8/14/2014
- Date at which the camera went live on the southbound approach: 10/01/2014
- Date at which the camera went live on the eastbound approach: 6/10/2015

After analyzing all of the available data, prior to the RLR camera installation, in 2011 there were 23 total crashes, 31 in 2012 and 23 in 2013, that is an average of 25.67 total crashes at 79th St and Cicero Ave per year. In 2015, one year after RLR camera installation, that number dropped to 16; a decrease of 37.67%.

Studies have reported that red light cameras reduce angle crashes. There proved to be a downward trend in angle crashes at 79th and Cicero Ave. In the year 2011 there was 1 angle crash, 0 in 2012 and 2 in 2013. In 2015, one year after installation, there were 0 angle crashes.